QUOTATION

Name of work: Rewinding and overhauling of ceiling fans installed at House No. 3007, 170, 474, 3061, 3070, 485, 3028, 4070, 3004 & 312 etc and other north side residences.

S.N	Description of work	Qty	. Unit	Rate (In words & Figures)	Amount
1	Rewinding of following fans of following so dismantling of rotor cutting the damaged wand providing rewinding along with inspaper, varnish, connecting copper leads of squality including dismentling and refixing normal/abnormal height and refixing as resolved to the contract of the cont	vinding sulation suitable g from			
a)	old model 48" / new model 56"	4.0	0 Nos.		
2	Overhauling of fan of any size inc dismantling and refixing of fan, bearings, che cleaning the all parts and supplying & replac of rubber real, rubber rings, nut bolts, he clamps, bearing plates, cotter/split pin, varn if reqd etc, reassembling testing commissioning of fan as reqdired complete.	ecking, cement	Nos.		
3	Supplying and fixing 2.5 mfd capacitor suital ceiling fan.	ole for 42.00	Nos.		
4	Repairing of housing of bearing side /bush side fan body in ceiling fan /exhaust fan/ rally fan e	de /in 9.00 etc.	Nos.		
5	Painting of ceiling fan any size with one or coats with supper enamel paint of approved by i/c cleaning and making smooth surface with e paper and detergent etc. as required.	orand	Nos.		
6	Cartage of Ceiling fans and regulator / exhaus From store to site as regd.	st fan 24.00	Nos.		
	Supply of following size ball bearings.				
1)	Ball bearing 6201 (NBC - make)	11.00	Nos.		
)	Ball bearing 6202 (NBC - make)	16.00	Nos.		
-	Total Rs.				
					/

RAGHVENDRA SINGH अधिशाषी अनियंता (वित) में E. (Elec सं वितिष्ठ , मार्जी कार्यात, समार्थ I.W.D., I.I.L. Kanput