## QUOTATION

Name of work :- Repairing and Overhauling of ceiling fans, Exhaust fans at Hall-1, H. No. 664, 497, V.H. Old D. Hall, Health Centre, CSEB lift machine room etc. as per enclosed complaints at IIT Kanpur.

S.No.	Description of work	Qty.	Unit	Rate (In words & Figures)	Amount
1	Rewinding of following fans of following sizes i/c dismantling of rotor cutting the damaged winding and providing rewinding along with insulation paper, varnish, connecting copper leads of suitable quality including dismentling and refixing from normal/abnormal height and refixing as required. (Old burnt wire shall be reatin by the contractor.)				
a)	old model 48" / new model 56"	7.00	Nos.		
2	Rewinding of exhaust fans of following sizes i/c dismantling cutting the damaged winding and providing rewinding along with insulation paper, varnish, connecting copper leads of suitable quality including dismentling and refixing from normal/abnorml height and refixing as required.( old burnt wire shall be retain by the contactor.)				
a)	Exhaust fan 15"	5.00	Nos.		
b)	Exhaust fan 18"	2.00	Nos.		
3.	Overhauling of ceiling fan of any size including dismantling and refixing of fan, bearings, checking, cleaning the all parts and supplying & replacement of rubber real, rubber rings, nut bolts, hanger	25.00	Nos.		
	clamps, bearing plates, cotter/ split pin, varnishing if reqd etc, reassembling testing and commissioning of fan as required complete.		36.3		

S.No.	Description of work	Qty.	Unit	Rate (In words & Figures)	Amount
4	Overhauling of exhaust fan of any size including dismantling of all parts and cleaning the fan with kerosene oil / petrol	2.00	Nos.		2
	removing ball bearing/ bush and refixing after greasing/ oiling including testing and commissioning as required complete. (spares will be supplied by the Dept.)				
.5	Supplying and fixing 2.5 mfd capacitor suitable for ceiling fan.	15.00	Nos.		
6	Repairing of housing of bearing side / bush side / in fan body in ceiling fan / exhaust fan/ rally fan etc.	8.00	Nos.		
7	Dismantling & disconnecting and refixing of exhaust fan from12" to 24 " size with required nut bolts, fasteners, rag bolts etc. as required.	2.00	Nos.		
8	Cartage of Ceiling fans and regulator / exhaust fan From store to site as reqd.	17.00	Nos.		
9	Supply of following size ball bearings.				
a)	Ball bearing 6201 (NBC - make)	8.00	Nos.		
b)	Ball bearing 6202 (NBC - make)	16.00	Nos.		

Total Rs.

अधिजाको प्रतिनिता विका छ छ । स्थानस् प्रतिनित्रक भावतिक सम्मान कार्युर । स्थातः, १.४.४, १.४.

2