QUOTATION

Name of work :-Repairing,servicing, cleaning & maintenance ceiling & exhaust fans in Type-II 2087, 2010, 2067, 2044, 2014, 216, 219, 281, 250, 268, Facalty Apartment-D104, B504, B403, A203, B604, D604, Old SBRA-P5, Z8, O2, M5, P1, R5, X11, AA13, AA19, M4, AA5,VFA-A2 etc.in the campus as per enclosed complaints.

. Description of work	Qty.	Unit	Rate (In words & Figures)	Amount
Overhauling of ceiling fan of any size including refixing of fan, bearings, checking, cleaning the all parts and supplying & replacement of rubber real, rubber rings, nut bolts, hanger clamps, bearing plates, cotter/split pin, varnishing if reqd etc, reassembling testing and commissioning of fan as required complete.				
ceiling fan / wall fan	49.00	Nos.		
exhaust fan	2.00	Nos.		
Supplying and fixing 2.5 mfd capacitor suitable for ceiling fan.	29.00	Nos.		
Repairing of housing of bearing side /bush side /in fan body in ceiling fan /exhaust fan/ rally fan etc.	6.00	Nos.		
Dismantling & refixing of any size following fan from normal height.				
Ceiling fan	49.00	Nos.		
exhaust fan	2.00	Nos.		
exhaust fan From store to site as reqd.	49.00	Nos.	¥	
	Overhauling of ceiling fan of any size including refixing of fan, bearings, checking, cleaning the all parts and supplying & replacement of rubber real, rubber rings, nut bolts, hanger clamps, bearing plates, cotter/split pin, varnishing if reqd etc, reassembling testing and commissioning of fan as required complete. ceiling fan / wall fan Supplying and fixing 2.5 mfd capacitor suitable for ceiling fan. Repairing of housing of bearing side /bush side /in fan body in ceiling fan /exhaust fan/rally fan etc. Dismantling & refixing of any size following fan from normal height. Ceiling fan exhaust fan Cartage of Ceiling fans and regulator /	Overhauling of ceiling fan of any size including refixing of fan, bearings, checking, cleaning the all parts and supplying & replacement of rubber real, rubber rings, nut bolts, hanger clamps, bearing plates, cotter/split pin, varnishing if reqd etc, reassembling testing and commissioning of fan as required complete. ceiling fan / wall fan 49.00 Supplying and fixing 2.5 mfd capacitor suitable for ceiling fan. Repairing of housing of bearing side /bush side /in fan body in ceiling fan /exhaust fan/rally fan etc. Dismantling & refixing of any size following fan from normal height. Ceiling fan 49.00 Cartage of Ceiling fans and regulator / exhaust fan From store to site as reqd.	Overhauling of ceiling fan of any size including refixing of fan, bearings, checking, cleaning the all parts and supplying & replacement of rubber real, rubber rings, nut bolts, hanger clamps, bearing plates, cotter/split pin, varnishing if reqd etc, reassembling testing and commissioning of fan as required complete. ceiling fan / wall fan 49.00 Nos. Supplying and fixing 2.5 mfd capacitor suitable for ceiling fan. Repairing of housing of bearing side /bush side /in fan body in ceiling fan /exhaust fan/ rally fan etc. Dismantling & refixing of any size following fan from normal height. Ceiling fan 2.00 Nos. Cartage of Ceiling fans and regulator / 49.00 Nos. Cartage of Ceiling fans and regulator / 49.00 Nos.	Overhauling of ceiling fan of any size including refixing of fan, bearings, checking, cleaning the all parts and supplying & replacement of rubber real, rubber rings, nut bolts, hanger clamps, bearing plates, cotter/split pin, varnishing if read etc, reassembling testing and commissioning of fan as required complete. ceiling fan / wall fan 49.00 Nos. Supplying and fixing 2.5 mfd capacitor suitable for ceiling fan. Repairing of housing of bearing side /bush side /in fan body in ceiling fan /exhaust fan/ rally fan etc. Dismantling & refixing of any size following fan from normal height. Ceiling fan 49.00 Nos. Cartage of Ceiling fans and regulator / exhaust fan From store to site as reqd.

S.No.	Description of work	Qty.	Unit	Rate (In words & Figures)	Amount
a)	Ball bearing 6201 (NBC - make)	8.00	Nos.		
b)	Ball bearing 6202 (NBC - make)	8.00	Nos.		
7	Rewinding of ceiling fans of following sizes i/c dismantling of rotor cutting the damaged winding and providing rewinding along with insulation paper, varnish, connecting copper leads of suitable quality including dismentling and refixing from normal/abnorml height and refixing as required. (Old burnt wire shall be reatin by the contractor.)	7			
a)	New model 48" & 56"	5.00	Nos.		
	ž.				

Total Rs.

ह े ने अभियंता (वित) है है (Flevi.) ह-, किन्द्रिक भावतीय के किन्द्रिक I.W.D., I.I.T., r...........