QUOTATION

Name of work :-Repairing, servicing, cleaning & maintenance ceiling fans & exhaust fans in Old SBRA-G1,M2,I2,S5,,New SBRA-Z5,AA8,Z7,Z3,Type-II.H.N0.214,257,279,286,2044,2073,2084,Type-IV-466, 4083, 4068,4065,473,4073 Type-507,Type-VI-664,657,669 in the campus as per enclosed complaints.

S.No.	Description of work	Qty.	Unit	Rate (In words & Figures)	Amount
1	Overhauling of ceiling fan of any size including refixing of fan, bearings, checking, cleaning the all parts and supplying & replacement of rubber real, rubber rings, nut bolts, hanger clamps, bearing plates, cotter/split pin, varnishing if reqd etc, reassembling testing and commissioning of fan as reqdired complete.				**
a)	ceiling fan / wall fan	60.00	Nos.		
2	Supplying and fixing 2.5 mfd capacitor suitable for ceiling fan.	25.00	Nos.		
3	Repairing of housing of bearing side /bush side /in fan body in ceiling fan /exhaust fan/ rally fan etc.	8.00	Nos.		
4	Dismantling & refixing of any size following fan from normal height.				
a)	Ceiling fan	60.00	Nos.		
5	Cartage of Ceiling fans and regulator / exhaust fan From store to site as reqd.	67.00	Nos.		
6	Supply of following size ball bearings.				
a)	Ball bearing 6201 (NBC - make)	12.00	Nos.	u g	
b)	Ball bearing 6202 (NBC - make)	17.00	Nos.		

S.No.	Description of work	Qty.	Unit	Rate (In words & Figures)	Amount
	Rewinding of ceiling fans of following sizes i/c dismantling of rotor cutting the damaged winding and providing rewinding along with insulation paper, varnish, connecting copper leads of suitable quality including dismentling and refixing from normal/abnorml height and refixing as required. (Old burnt wire shall be reatin by the contractor.)				
a)	New model 48" & 56"	2.00	Nos.		

Total Rs.

अधिकाषी अभिगंता (चित्र) E.E. (Elect.) सं. . चित्र पार्टी के संस्थान, मानपुर LW.D., La. I., Kanpur