QUOTATION

S/Replacement of "Digital Controller (PROCOM)" at AMF (Elect.) panel of 320 kVA DG (Old) @ SS#1 and Sub: Rewinding/maintenance of Self "Starter motor" of 250 kVA DG(Old) @ SS#1, 500 kVA DG @ SS#11. (Not cover in existing AMC)

S.No	Description	Qty.	Unit	Rate	Amount
		a 5		(In words & Figures)	Amount
1	Supply of "Digital Controller" make (PROCOM) PHI /Equv. of AMF panel i/c cartage and frieght etc complete as required.		Nos.		
2	Charges for fault finding and assessment and installation of Digital Controller" make (PROCOM) PHI /Equv in existing AMF/Electrcal panel i/c DLP for 06 Months complete as required.		Nos.		
3	Programming & commissioning of "Digital Controller" make (PROCOM) PHI /Equv. of AMF panel i/c old dismantling if any complete as required.	1.00	Nos.		
4	Rewinding of field and armature i/c replacemet of clutch, carbon set, switch, lever and pinion of Greaves make DG "Self Starter (motor)" i/c cartage and frieght etc complete as required.				
1	250/320 Kva DG "Self Starter (motor)"	1.00	Nos.		
1	500/750 Kva DG "Self Starter (motor)"	1.00	Nos.		
	Total Rs.			1	

ছাংগরিগেরিগ,(I.W.D.), भाजकीश-सहसान, जा हु A.L.T. Kansaya