

QUOTATION

Name of Work:-Repairing and maintenance of geysers in installed in New SBRA-AA-15, X-8,AA-20, X-3, AA-22, Z-16, VFA-A-3, Ratan planet-B-306, B-105, B-803 as per enclosed complaints.

S.No	Description of Items	Qty	Unit	Rate (In words & Figures)	Amount
1	Locating fault in geyser rectifying removing & restoring supply the same & making good the damages etc as reqd.	3.00	Nos		
2	Supply fixing connecting & commissioning of 2 kW heating element with flange in geyser. as required complete	5.00	Nos.		
3	Supply fixing connecting & commissioning of 2 kW heating element without flange in geyser. as required complete	7.00	Nos.		
4	Supply fixing connecting & commissioning of capillary type thermostat suitable for Solar water tank / geyser as required complete	5.00	Nos.		
5	Supply fixing connecting & commissioning of thermostat suitable for Solar water tank / geyser as required complete	6.00	Nos		
6	Supply fixing connecting & commissioning of capillary type reset suitable for Solar water tank / geyser as required complete	5.00	Nos.		
7	Supply fixing connecting & commissioning of reset suitable for Solar water tank / geyser as required complete	7.00	Nos		
8	Dismantling and refixing of switch / socket / geyser l/c cleaning, connecting, commissioning etc as reqd.	6.00	Nos		

S.No	Description of Items	Qty	Unit	Rate (In words & Figures)	Amount
------	----------------------	-----	------	------------------------------	--------

9	S&F Copper pipe with coupling and washers in the existing geyser complete as per direction of site incharge(one set contain two copper tube with 4no copper nuts and washers)	7.00	Set.		
---	--	------	------	--	--

Total Rs



अभिषेक अभियन्ता (सि)/E.P. (सि.)
 संतोषी, माठ प्रौ संस्थान, काठनपुर
 I.W.D. I.I.T. Kaupur
